
MediPaw[®] Healing Slim Boot Measurement Chart





- Print the Sizing Chart at 100% size.
- Verify the accuracy of this chart with a ruler before measuring.





MEASUREMENT TIPS:

- Measure the width of the paw and the bandage (if applicable) to ensure a correct fit.
- If you can't print the chart, draw a line on either side of the patient's on blank paper, measure the widthand refer to the chart above.

Questions? Please contact us! info@medivetproducts.com P; 800.245.3413 F: 646.783.3808

www.medivetproducts.com

Protective Boot U.S. Patent No: 8,161,668

